
TX1000A and RX1000A

Wireless Doorway Announcer


Parts Included

- TX1000A Indoor Transmitter
- RX1000A Indoor Receiver
- Aluminum Transmitter Bracket
- Mounting Screws X4



Required Items

- AA Batteries X3
- P1 Philips Screwdriver



Getting Started

The **TX1000A** requires 3 AA batteries.

To install the batteries, simply pull back and lift up on the tab located on the back of the unit.

The **RX1000A** comes equipped with a 12VDC plug-in power supply with a 5ft cord.

DIP Switches

IMPORTANT: There is no need to change these DIP switches unless you are experiencing false rings from neighboring devices.

(If DIP switches are changed, switches 1 - 4 must be the $\textbf{SAME} \;$ on $\textbf{BOTH} \; \text{TX} \; \& \; \text{RX} \; \text{units!})$

nits!)




"To register any DIP switch change, you will need to disconnect power from the unit you are making the changes on"


Selecting the Tones

Tones are set on the TX only!

- 1. 5 and 6 down = Ding Dong (Default)
- 2. 5 up and 6 down = Single Ding
- 3. 5 down and 6 up = Double Ding Dong
- 4. 5 and 6 up = Turbo Sound




"To register any DIP switch change, you will need to disconnect power from the unit you are making the changes on."



The RX Unit

DIP switches **5 & 6** on the **RX** unit control the length of time the 12VDC terminal receives power when using an external wired accessory such as a **siren**, **buzzer** or **strobe**.



The **SPKR** terminal is used to attach external speakers **only**.





If no 12VDC accessory is attached, DIP switches 5 & 6 create a **delay between tones.**


- 5 up 5 sec. delay / 5 sec. of power
- 6 up 20 sec. delay / 20 sec. of power

TX1000A and RX1000A Installation Instructions

The TX1000A can be installed above the doorway, on the ceiling or mounted on the side.







"Avoid installing the TX1000A near heating or cooling vents, close to fluorescent or neon lighting or in direct sunlight. This may cause false rings or prevent customer detection."

